





Measurement

Simultaneous current measurement on 3 phases without cutting the circuit.



Calibration

Current injection on the equipment, without disturbing the current transformer, with the special use of the H adaptor (current transformers side shunted).



Solution 1: FIC-2/4 plug with the special use of the H adaptor (current transformers side shunted).

Solution 2: specific prewired plug COR-C-2 or COR-C-5 (prewired plug with short circuited inner contact pins: 1-2-3-4 side).