





Measurement


Voltage measurement with TC type voltage socket (make before break) and 2x4 poles plug:



Voltage measurement with TO type voltage socket (opened) and 4 poles plug:




Voltage measurement with TF type voltage socket (closed) and 4 poles plug:





Calibration

Voltage injection with TC type voltage socket (make before break) and 2x4 poles plug.



Calibration

Voltage injection with TO type socket (opened) and 4 poles plug.

